

HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

May 4, 2010

Steve Silberberger, Administrator Seven Oaks Community Homes-- Pinnacle 3940 West 5th Avenue #C Post Falls, Idaho 83854

RE: Seven Oaks Community Homes-- Pinnacle, Provider #13G076

Dear Mr. Silberberger:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Seven Oaks Community Homes - Pinnacle, on April 19, 2010.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208) 334-6626.

Sincerely,

TOM MROZ

Health Facility Surveyor

Facility Fire Safety and Construction Program

TM/li

Enclosure

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 04/26/2010 FORM APPROVED OMB NO. 0938-0391

(X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING B. WING_ 13G076 04/19/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

2000 NODTH DINNACLE LAND

(X4) ID	SUMMARY STATEMENT OF DEFICIENCIES	ID	PROVIDER'S PLAN OF CORRECTION	(X5)
PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	PREFIX TAG	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	COMPLETION DATE
K 000	INITIAL COMMENTS	K 000		
	Surveyor: 27570			
	The facility is a single story, 1,500 s.f., residential structure of Type V(000) construction. The building construction was completed in December of 2005. It has a complete fire alarm/smoke detection system. There is a 13 -D modified sprinkler system with quick response heads that covers all living spaces and closets. There are two emergency battery pack lights and two portable fire extinguishers. The facility is licensed for 5 ICF/MR beds.			
	The facility was found to be in substantial compliance with applicable fire/life safety requirements during the annual fire/life safety survey conducted on April 19, 2010. The facility was surveyed under the Life Safety Code, 2000 Edition, Chapter 32, New Residential Board & Care Occupancies, Impractical Evacuation Capability in accordance with 42 CFR 483.470 (j).			
	The survey was conducted by:			
	Tom Mroz CFI-II Health Facility Surveyor Fire/Life Safety and Construction			
		7470.0004		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 04/26/2010 FORM APPROVED

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 02

(X3) DATE SURVEY COMPLETED

13G076

B. WING _

04/19/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

SEVEN OAKS COMMUNITY HOMES - PINNACLE 908 NORTH PINNACLE LANE POST FALLS, ID 83858					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY REGULATORY OR LSC IDENTIFYING INFORMA	FULL PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
M 000	16.03.11 Inital Comments	M 000	·		
	Surveyor: 27570 The facility is a single story, 1,500 s.f., r structure of Type V(000) construction.				
	building construction was completed in December of 2005. It has a complete fin alarm/smoke detection system. There is modified sprinkler system with quick resheads that covers all living spaces and the There are two emergency battery pack two portable fire extinguishers. The facticensed for 5 ICF/MR beds.	re s a 13 -D sponse closets. lights and			
	The facility was found to be in substanti compliance with applicable fire/life safet requirements during the annual Fire/Life survey conducted on April 19, 2010. The was surveyed under the LIFE SAFETY 1976 Edition, Residential Board & Care Occupancies, Impractical Evacuation C in accordance with IDAPA 16.03.11	cy e Safety e facility CODE,			
	The Survey was conducted by: Tom Mroz CFI-II Health Facility Surveyor Fire/Life Safety and Construction				
ABORATOR	Y DIRECTOR'S OR PROVIDER/SUPPLIER REPRESEN	NTATIVE'S SIGNATURE	TITLE	(X6) DATE	

WB7721